## GALT JOINT UNION ELEMENTARY SCHOOL DISTRICT

## Fairsite Elementary Portables Renovation

## ADDENDUM #1

DATE: March 21, 2023

PROJECT:

Fairsite Elementary Portables Renovation Fairsite Elementary School 902 Caroline Avenue Galt, CA 95632


OWNER:

Galt Joint Union Elementary School District 1018 C Street, Suite 210 Galt, CA 95632

## The following are the questions received and our response:

- 1. Confirm the bid date and time listed above are unchanged.
  - Correct, the bid date and time listed have not changed.
- 2. Construction cost estimate or a construction cost range for the project.
  - The District does not have a predetermined cost estimate or range.
- 3. Mandatory pre-bid Attendance List
  - This can be found on our website at: <u>https://gjuesd-</u> ca.schoolloop.com/pf4/cms2/view\_page?d=x&group\_id=1500178971369&vdid=ix19for3 b47n28kb
- 4. Any addenda that have been released, please attach them to this response.
  - By the District response date in the RFP any addendum can be found on our website at: <a href="https://giuesd-ca.schoolloop.com/pf4/cms2/view\_page?d=x&group\_id=1500178971369&vdid=ix19for3\_b47n28kb">https://giuesd-ca.schoolloop.com/pf4/cms2/view\_page?d=x&group\_id=1500178971369&vdid=ix19for3\_b47n28kb</a>
- 5. Can you please provide a map with the exact location of all portable buildings which are a part of this project?
  - Map is attached to this addendum, portables are shaded and consist of:
    - i. Rooms 1 & 2: Metal portables, exterior paint only.
    - ii. Rooms 15, 16, 17, 18, 22, 25, 26, 27, 28, 29, 30, 32 and the pre-school office, dry rot repair where needed and exterior paint.

- 6. Can you please identify the required dry rot damage for each portable building?
  - Dry rot was discussed during the job walk, each participant should use professional judgement on the extent of the needed repair to each.
- 7. What is extent of the dry rot repair? Do we need to replace the entire T1-11 / skirting panel, fascia section, etc.?
  - Dry rot was discussed during the job walk, each participant should use professional judgement on the extent of the needed repair to each. The minimum height of T1-11 replacement would be 2 feet.
- 8. Do we need to replace all gutters and downspouts for 15 portables?
  - Gutter/downspouts are as needed, where gutter/downspout needs replacement or is missing.
- 9. Can you please provide any specification for the new gutters and downspouts?
  - Galvanized gutters and downspouts
- 10. Who is responsible for removing any conduits during the dry rot repair?
  - Contractor's responsibility
- 11. Who is responsible for removing any HVAC units (if needed) during the dry rot repair?
  - HVAC units are to not be removed, repair will occur around the units.
- 12. Are the paint colors going to match existing, similar or away different colors?
  - The District has the Kelly Moore paint colors to provide contractor that match existing paint colors.
- 13. Are there plans available?
  - There are no plans for this specific project.
- 14. Is the DVBE a requirement?
  - Yes, if you are using sub-contractors the attempt should be made due to the funding source paying for this project.
- 15. Is there an Asbestos, Lead Abatement Project Specification? If applicable.
  - Non-applicable.



Updated: 8/4/2022